



COLORADO PASSENGER TRAMWAY SAFETY BOARD
PASSENGER TRAMWAY INCIDENT REPORT

Pursuant to Rule 23.2 of the Colorado Passenger Tramway Safety Board Rules and Regulations, during public operation, all "passenger tramway incidents" must be verbally reported to the Board as soon as reasonably possible, but no later than twenty-four (24) hours after the time of such an incident. A written report must be submitted to and received by the Board, via email, fax or via USPS, within five (5) days of such incident.

Name of Board Staff Member to whom this incident was orally reported: Brooks Beal

Incident was orally reported on Date: 12-21-2024 at Time: 12:30 AM/PM (PM)
(Month/Day/Year)

Please complete the following information: *(Use separate sheet, if additional space is required.)*

A. Name of Area: Winter Park Resort

B. Lift ID No. WP-039 Name of Tramway: Zephyr Gondola

C. Date of Incident: 12-21-2024 Time: 12:15 AM/PM (PM)
(Month/Day/Year)

D. Location of Incident: Heavy side of tower #1

E. Failure Code(s) *(Required - Form 141-03)*: 4.7, 4.7.1, 4.7.5, 7.5

Description: Crack in main evenier sheave train beam on
heavy side of tower #1

F. Cause Code(s) *(Required - Form 141-03)*: 2.3

Description: Fatigue

G. Action taken as a result of this incident, if any: Replaced main evenier beam

H. Length of time the tramway was down (Initial stop to reopening to the public): 48 hours, 56 minutes
12:15 pm on 12-21-2024 until 1:11 pm on 12-23-2024

OR ☐ Tramway was not open to the public

Names, addresses and statements of witnesses: ☒ On File with Area ☐ Not applicable

I. Nature of extend of injuries that may have been suffered, including names and addresses of injured:

☒ Not applicable

No injuries

J. Designate how tramway was stopped, detail below or: ☐ Not applicable

Return guide sheave heavy side CPS fault, return grip attach fault

K. Evacuation: ☐ NO ☒ YES If YES, ☒ Rope (R) OR ☐ Evac Power Unit (EPU)

Note: Evacuation by Rope or Evac Power Unit - NOT by Diesel Prime Mover

L. Number of affected persons 182 AND total time for evacuation from time tramway first stopped to the end of the evacuation: 5 hours 51 minutes

M. Print Name AND Title of person reporting: Brad Hawkins Sr Manager Lift Maintenance
Signature of person reporting: [Signature]

N. Print Name of Designated Agent: Sally Foulkes
Signature of Designated Agent: [Signature]

Fully complete and submit this form via email or fax or USPS mail to:

Colorado Passenger Tramway Safety Board
DORA/Division of Professions & Occupations
1560 Broadway, Ste 1350
Denver CO 80202
FAX: 303-869-0235
Email: DORA_TramwayBoard@state.co.us

Telephone numbers are listed herein to aid in compliance with Rule 23.2 of the Colorado Passenger Tramway Safety Board Rules and Regulations:

Office: 303-894-7800

Brooks Beal, PE, Supervisory Tramway Engineer
Joyce Young, Program Director

Office:
303-894-7781

Cell:
303-929-3494
720-820-0898